

**MARYLAND HISTORICAL TRUST
NR-ELIGIBILITY REVIEW FORM**

NR Eligible: yes ☒
no ☐

Property Name: Dutrow-Thomas Farm Inventory Number: F-1-175

Address: 3040 Ballenger Creek Pike City: Frederick Zip Code: 21701

County: Frederick USGS Topographic Map: Buckeystown

Owner: Calico Land 17800 Bowie Mill Road, Derwood, MD 20855

Tax Parcel Number: 98 Tax Map Number: 94 Tax Account ID Number: 1101025627

Project: _____ Agency: _____

Site visit by MHT Staff: ☐ no ☐ yes Name: _____ Date: _____

Eligibility recommended ☒ Eligibility **not** recommended ☐

Criteria: ☒ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ None

Is the property located within a historic district? ☒ no ☐ yes Name of district: _____

Is district listed? ☐ no ☐ yes Determined eligible? ☐ no ☐ yes District Inventory Number: _____

Documentation on the property/district is presented in:

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*

The current assessment was prepared on behalf of Duke Energy North America as part of cultural resources investigations to support the proposed construction of a power plant in southern Frederick County near Point of Rocks (Goodwin 2001). The assessment is based on previously existing documentation available at the Maryland Historical Trust confirmed by a reconnaissance survey of the property taken from the public right of way.

In 1993, this farmstead comprised a ca. 1835 farmhouse, a smoke house, wood shed, slave quarters, garage, chicken house and brooder house, springhouse, bank barn, dairy barn with silo, milk house, wagon shed/corn cribs, and tenant house (Davis 1993). This property is not easily visible from the right of way of any public roadway. A windshield survey of the property confirmed the presence of the house and barns. No details of the other buildings surveyed in 1993 were visible during the windshield survey.

Davis (1993) stated that the "Dutrow-Farmstead is significant as a good example of the nineteenth century farmstead established about 1835 with continuing changes and alterations throughout the early twentieth century to about 1940." As such, the farmstead illustrates an important period of agricultural history in Frederick County (Criterion A). The house and outbuildings also embody the distinctive characteristics of types, periods, and methods of construction (Criterion C). The house also has notable Greek Revival ornamentation and an unusual plan with a cross hall.

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended <input checked="" type="checkbox"/>	Eligibility not recommended <input type="checkbox"/>
Criteria: <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: _____	

Reviewer, Office of Preservation Services <i>[Signature]</i>	Date <i>6/14/2002</i>
Reviewer, NR program <i>[Signature]</i>	Date <i>7/19/02</i>

**MARYLAND HISTORICAL TRUST
NR-ELIBILITY REVIEW FORM**

Continuation Sheet No. 1

F-1-175

Bibliography

Davis, Janet L.
1993 Dutrow-Thomas Farmstead (F-1-175). MIHP form available at the Maryland Historical Trust, Crownsville, MD.

Goodwin, R. Christopher, & Associates, Inc.


June 2001 Architectural and Historical Investigations for the Proposed Duke Energy North America Facility on the Offutt Property, Frederick County, Maryland. Prepared by RCG&A, Inc., for Environmental Consulting & Technology, Inc., Tampa, Florida.

Nov. 2001 Supplemental Architectural and Historical Investigations for the Proposed Duke Energy Facility on the Vernon-Hines and Urciolo Properties, Frederick, Maryland. Prepared by RCG&A, Inc., for Environmental Consulting & Technology, Inc., Tampa, Florida.

Prepared by: Katherine Grandine and Brian Clevon,
R. Christopher Goodwin & Associates, Inc.

Date Prepared: March 2002

F-1-175
 Dutrow-Thomas Farm
 Adamstown Vicinity
 Frederick County, Maryland
 Buckeystown USGS quadrangle map
 Scale 1:24,000





6 302

F-1-175

Dutrow-Thomas Farm

Frederick Co, Md

K. Grandine

3/2002

Md SHPO

Overview, view W

1/3



F-1-175

Dutrow - Thomas Farm

Frederick Co. Md

K. Grandine

3/2002

Md SHPD

Dwelling, view W

2/3



S 302

F-1-175

Dutrow-Thomas Farm

Frederick Co. Md

K. Grandne

3/2002

Md SHPO

Barns, view W

3/3

F-1-175
Dutrow-Thomas Farmstead
Adamstown vicinity
Private

Ca. 1835-1940

The Dutrow-Thomas Farmstead is an agricultural complex centered on a circa 1835 brick dwelling with clearly defined domestic and agricultural outbuildings groups ranging in date from about 1835 to about 1940. The house, built about 1835 by Samuel Dutrow, has an unusual plan with a cross hall and fine Greek Revival trim in the parlor. In the original dining room is a vernacular craftsman's version of a Federal style highboy with a broken pediment and grained surfaces. The domestic outbuildings include a one-story brick slave quarters with two rooms, a loft, and a Federal style mantel at the center fireplace, and a brick springhouse, both built about the same time as the house. Later outbuildings include frame chicken houses, a garage of the about 1890-1900, and a wood shed. The agricultural group has a very large frame bank barn built in 1913, two wagon shed/corn cribs, and a non-contributing concrete block dairy barn and milk house. A frame tenant house of about 1875-1900 is also on the property, as well as several other non-contributing outbuildings. The farmstead is a good example of the transition of the 19th century farmstead from about 1835 to 1940, with representative buildings of the mid and late 19th century as well as the first half of the 20th century. The farm was called "Red Hill" over much of its history, and was purchased by Joseph C. Thomas in 1911 from the descendants of Samuel Dutrow.

F-1-175
Dutrow-Thomas Farmstead
Adamstown
Frederick County

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Piedmont
(Harford, Baltimore, Carroll, Frederick, Howard, Montgomery
Counties, and Baltimore City)

Chronological/Development Period:
Agricultural-Industrial Transition A.D. 1815-1870
Industrial/Urban Dominance, A.D. 1870-1930
Modern Period, A.D. 1930-Present

Prehistoric/Historic Period Themes
Agriculture
Architecture, Landscape Architecture and Community Planning

Resource Type:

Category: Building

Historic Environment: Rural

Historic Function & Use:
Domestic/single dwelling/residence
Domestic/secondary structure/other dependencies
Agriculture/subsistence/animal facility/barn
Agriculture/subsistence/animal facility/chicken coop
Agriculture/subsistence/storage/granary

Known Design Source: None

Maryland Historical Trust

State Historic Sites Inventory Form

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

Magi No.

DOE ☐ yes ☒ no

1. Name (indicate preferred name)

historic Dutrow-Thomas Farmstead (preferred); Red Hill

and/or common

2. Location

street & number 3040 Ballenger Creek Pike ☐ not for publicationcity, town Adamstown ☒ vicinity of congressional district 6th

state Maryland county Frederick

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Joseph C., Jr., & Dorothy B. Thomas

street & number P.O. Box 26 telephone no.:

city, town Adamstown state and zip code MD 21710

5. Location of Legal Description

courthouse, registry of deeds, etc. Frederick County Courthouse liber 917

street & number 100 W. Patrick Street folio 292

city, town Frederick state MD 21701

6. Representation in Existing Historical Surveys

title

date ☐ federal ☐ state ☐ county ☐ local

pository for survey records

city, town state

7. Description

Survey No. F-1-175

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

SECTION 7: Description:

CONTRIBUTING RESOURCE COUNT: 9

The Dutrow-Thomas Farmstead is an agricultural complex centered on a circa 1835 brick dwelling with a side wing and its associated domestic and agricultural outbuildings dating from about 1835 to about 1940, located on the west side of Ballenger Creek Pike just south of Mountville Road, near Adamstown, Frederick County, Maryland. The farmstead is located at the end of a long driveway in the center of open agricultural fields with the buildings generally organized in two groupings, the agricultural group being nearer the driveway entrance on Ballenger Creek Pike and the domestic grouping about 100 yards further to the southwest. The dates of the buildings were estimated from architectural evidence, land records, and personal interviews with the owner, Mrs. Joseph C. Thomas.

The house is a two-story brick building facing east with a two-story side service wing on the south gable end of the four-bay main section. The walls are laid in 5:1 American bond and interior chimneys are located at the north and south gable ends. The roof is standing seam metal. The cornice is corbeled, and the window and door openings have wood lintels with bull's-eye corner blocks. The windows are 6/6 with louvred shutters. The first story is sheltered by a flat roofed porch with turned columns, probably an addition made in the last quarter of the 19th century. The entrance is in the left center bay and has a 10-panel door with a transom featuring diamond patterned muntins. The side wing has a recessed east wall fronted by a two-level open porch. Two entrances occupy the center bays of the four bays on the first story of the side wing and a third entrance is in the end wall of the main section. On the west elevation of the house are two modern additions, one located off the side wing and the other a sun room off the main section.

The interior plan of the house reveals a cross hall in the main section in which the staircase is located against the east wall, rising past the window in the outer bay. The rest of the main section's first floor is occupied by two rooms, a parlor on the north end and the probable original dining room located off the long side of the stair hall. The interior details of the main section show the transition between the Federal style and the Greek Revival style. In the stair hall, the closer is ornamented with a scroll design. The interior doors are grained and the entrance to the parlor has a paneled soffit. The parlor, a 24 by 17-ft. room, has a plaster molded cornice and the ceiling originally had a molded plaster center medallion which has been removed because of deterioration. The brick mantel is a modern feature, replacing the original mantel. The window and door surrounds have rosette corner blocks and reed molding surrounds. The floor in both the parlor and the hall is covered with hardwood installed in the 1950's. The walls are painted plaster. The west wall has two bays with a 10-panel door which formerly opened to the outside, but now leads to the modern sun room. The former dining room has wallpaper and a Greek Revival style molded mantelpiece flanked by a built-in grained cupboard. This cupboard has a vernacular version of a broken pediment with simp.

8. Significance

Survey No. F-1-175

Period	Areas of Significance—Check and justify below			
___ prehistoric	___ archeology-prehistoric	___ community planning	___ landscape architecture	___ religion
___ 1400-1499	___ archeology-historic	___ conservation	___ law	___ science
___ 1500-1599	<input checked="" type="checkbox"/> agriculture	___ economics	___ literature	___ sculpture
___ 1600-1699	<input checked="" type="checkbox"/> architecture	___ education	___ military	___ social/
___ 1700-1799	___ art	___ engineering	___ music	___ humanitarian
<input checked="" type="checkbox"/> 1800-1899	___ commerce	___ exploration/settlement	___ philosophy	___ theater
<input checked="" type="checkbox"/> 1900-	___ communications	___ industry	___ politics/government	___ transportation
		___ invention		___ other (specify)

Specific dates C, 1835-1940

Builder/Architect

check: Applicable Criteria: ☒ A ___ B ☒ C ___ D
and/or

Applicable Exception: ___ A ___ B ___ C ___ D ___ E ___ F ___ G

Level of Significance: ___ national ___ state ☒ local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Dutrow-Thomas Farmstead is significant as a good example of the 19th century farmstead established about 1835 with continuing changes and alterations throughout early 20th century to about 1940. The architecture of the circa 1835 brick dwelling is particularly important, with Greek Revival and transitional Federal details, as well as an unusual floor plan with a cross hall. This plan is also present in a dated 1840 brick dwelling which was probably originally begun between the period 1820-1840, the Zimmerman Farmstead (F-1-176), located about two miles from the Dutrow-Thomas Farmstead. The two houses have similar Greek Revival details in the mantelpieces, doors, and staircase trim. The Dutrow-Thomas House has the unique built-in cupboard with a broken pediment. The architecture of the other buildings in the Dutrow-Thomas Farmstead is typical for the different periods of construction represented, but the surviving number and type of buildings is uncommon in the Adamstown Region where agricultural land use is increasingly giving way to residential development.

The farmstead was apparently established by 1835 by Samuel Dutrow (1796-1873), for whom the tract "York", totaling 304.75 acres was surveyed as of July 10, 1835. Dutrow (also spelled Dutterer in some deeds) was the owner of several farms in the Adamstown Region and William J. Grove, in his History of Carrollton Manor (1928) described him as "a very thrifty intelligent farmer, who owned Red Hill." This name was not mentioned in the land records, but it was apparently in common use over the history of the tract, being also applied to a schoolhouse in the vicinity. Although it is not entirely clear which of several Samuel Dutrows who lived in the region in the 19th century is the subject, Samuel Dutrow was also described by Grove as a promoter of road improvement in the Carrollton Manor tract, as he traveled to market in Frederick several times each week. He was a subscriber to the Buckeystown-Frederick turnpike company. The home farm was devised by his will to his son Samuel whose heirs sold the farm to Joseph C. and Edith F. Thomas in 1911. The current owner is Mrs. Joseph C. Thomas, Jr.

9. Major Bibliographical References

Survey No. F-1-175

Bond, Isaac. Map of Frederick County, 1858.

Grove, William J. History of Carrollton Manor, Frederick: Marken & Bielfeld, Inc., 1928, p. 99

Land Records of Frederick County

(Continued on separate sheet)

10. Geographical Data

Acreage of nominated property 20 acresQuadrangle name Buckeystown, Md.Quadrangle scale 1:24000UTM References do NOT complete UTM referencesA

Zone			Easting			Northing			

B

Zone			Easting			Northing			

C

--	--	--	--	--	--	--	--	--	--

D

--	--	--	--	--	--	--	--	--	--

E

--	--	--	--	--	--	--	--	--	--

F

--	--	--	--	--	--	--	--	--	--

G

--	--	--	--	--	--	--	--	--	--

H

--	--	--	--	--	--	--	--	--	--

Verbal boundary description and justification

Approximately 20 acres centered between the main dwelling house and the agricultural group containing the two barns on Tax Map 94, Parcel 27.

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

11. Form Prepared By

name/title Janet L. Davis, Historic Sites Surveyororganization Frederick County Planning & Zoning Dept. date April 1993street & number 12 E. Church Street telephone 696-2958city or town Frederick state MD 21701

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

MARYLAND HISTORIC TRUST
DHCP/DHOC
400 COMMUNITY PLACE
BETHESDA, MD 20814-2003
APR 1993

7.1 Description (Continued)

rosettes at the center of the scrolls and a plain rounded outline in the place of the typical classical urn in the center. The side wing has two rooms, the center room having a columned Greek Revival mantel flanked by a built-in cupboard. This cupboard is simpler in design and has paneled doors. The other room in the wing is the modern kitchen, in which the original cooking fireplace has been removed.

Domestic outbuildings:

Smokehouse: The concrete block smokehouse is a non-contributing late 1940's building which replaced the original smokehouse in the domestic group.

Wood shed: Immediately west of the smokehouse is an open-sided frame shed with vertical siding and a corrugated metal shed roof, which serves as a wood shed. The building appears to date from the first quarter of the 20th century.

Slave quarters: The one-story brick building is identified by Mrs. Thomas as slave quarters rather than a summer kitchen and this is supported by its siting somewhat further from the house than the typical summer kitchen location and by its interior finish. The building is also 5:1 bond as is the main dwelling. The corrugated metal gable roof covers original wood shingles and an off-center chimney rises from the roof. The building has two rooms, the northern having a large open fireplace with a blackened Federal style mantel with a fluted frieze panel. Winding stairs lead to the upper level loft. A 6/6 window is located next to the 4-panel door in the east elevation and a second window is in the west elevation. The other room in the building apparently served as a storage room, with open shelves around the walls. The floor in this room, as in the other room, is wide boards, but is much deteriorated. The building most recently was used for butchering activities. The quarters were probably built at the same time as the house, about 1835.

Garage: Immediately east of the slave quarters is a frame garage built about 1890-1900 with tongue-and-groove siding, a standing seam gable roof, and double swing doors.

Chicken house and brooder house: The frame chicken house with board and batten siding is located east of the garage. Traces of whitewash are visible on the exterior. It has a standing seam metal roof. The brooder house is a rectangular structure with tongue-and-groove siding and a standing seam metal roof located south of the chicken house with a non-contributing shed in between the two structures. The chicken houses probably date from the early 20th century, as Mrs. Thomas states that several chicken houses were located during that period throughout the domestic and agricultural groups to supply the needs of the large farm and for local sales and trades to the surrounding farms. More recently, the chicken houses have been used for sheep pens. At least one other non-contributing structure in the domestic group is a sheep pen.

Springhouse: The brick springhouse is located on the east side of the driveway between the domestic and agricultural groups. It was probably built in the

7.2 Description (Continued)

1830's with the main house and the slave quarters. It has 5:1 American bond walls and a tongue-and-groove door on the west elevation. The gable roof is covered with standing seam metal. The spring is located just west of the building and flows through the foundation into a trough in the ground level.

Agricultural outbuildings:

Bank barn: The frame bank barn with a stone foundation was built in 1913, according to Mrs. Thomas. It is 112 feet by 60 feet and is reputed to be one of the largest in southern Frederick County. It has vertical board siding and a corrugated metal roof. The stall level on the south elevation is enclosed by horizontal boards in both flush and open applications. The barn has four sliding doors on the south elevation and two sets of similar doors on the north elevation.

Dairy barn, milk house, and silo: The concrete block dairy barn, milk house, and silo were built about 1950 and are non-contributing structures in the farmstead.

Wagon shed/corn cribs: Two frame wagon sheds are located north and northeast of the bank barn. The older of the two was probably built in the last quarter of the 19th century and has a narrow drive through opening with larger cribs flanking the opening. The newer of the two has a wider opening and correspondingly narrower cribs. Both have vertical siding and corrugated metal roofs. The older wagon shed has an intact wood pulley for changing wagon carriages to serve varied agricultural tasks, such as closed bed to flat bed.

Tenant house: The frame tenant house is unoccupied and deteriorating, standing in a field about 50 yards east of the driveway between the domestic and agricultural groups. It was not observed in detail, but appears to have artificial siding over original german siding and the outline of a one-story porch, now missing on the west elevation. The main elevation has three bays on the first story with a center entrance and two bays on the second story. The roof is standing seam metal and an interior chimney is located on the north gable end. The house appears to have been built during the period 1875-1900. Mrs. Thomas plans to demolish the house by controlled burn under fire company supervision.

Dutrow-Thomas Farmstead
Frederick County


SURVEY No. F-1-175

9. Bibliography (Continued)

Titus, C.O. Atlas of Frederick County, 1873.

Williams, T.J.C., and Folger McKinsey. History of Frederick County, 1910.
Reprinted Baltimore: Regional Publishing Co., 1979, p. 1282.

N →



F-1-175

Dutrow-Thomas Farmstead
Frederick County


Janet Davis
April 15, 1993

Not to Scale

Dutw Farmstead

Liber/Folio	Grantee	Grantor	Lot Size, Description, Other Information, Original Tracts	Cost	Miscellaneous
1573/246 22 June 89					
917/292 29 June 73	Joseph C. Jr. & Dorothy B. Thomas	Joseph C. Thomas Jr.	294.57 A.		
917/290 29 June 73	Joseph C. Thomas Jr.	Joseph C. Thomas Jr., et al Pers. repr. of estate of Edith J. Thomas, dec.			Will Record TME 7/141
HWB 296/185 3 Apr 11	Joseph C. & Edith J. Thomas	Samuel P. Dutrow et al (children of Samuel & Catherine Dutrow)	"Hfork" resurveyed by H. G. O'Neale, surveyor, warrant to Samuel Dutrow or Dutrow, 10 Jul 1835	\$20,000	3 04 1/4 A.
Will Record S GC 1/427 12 Nov 1872	Samuel Dutrow & Catherine Dutrow wifely	Samuel Dutrow			1796-1873? W4 mck 1283
Survey Record TH 09/526 23 Nov 1835	"Hfork" contains parts of following tracts: "Sacking Plan" 50 A. "Halsey's Folly" 43 A. ± "Resurvey on Lashmutts Folly" 58 A. "Long Hape" 24 A. ± "Perfection Disputed" 89 A. ± "1st part of Burgess's Lot" 26 A. "2nd part of Burgess's Lot" 12 A. ± + 15 A. vacant or renamed				

Scale $1\frac{1}{2}$ inches to an mile



Buckevstown Dist.

Scale 20 Rods to an Inch

(Geagerstown Dist)

Scale 20 Rods to an Inch



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md

East elevation

1/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

West elevation

2/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

Parlor doorway and staircase

3/13



F-1-1745

Dutton-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md

Main door detail

4/13



F-1-175

Dutrow-Thomas Farmstead
Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

Dining room cupboard

5/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO. Crownsville, Md

Second floor mantel

6/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc. in Md SHPO, Crownsville, Md.

Garage and slave quarters/summer kitchen,
view from east

7/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

Springhouse, west elevation

8/13



F-1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md

Bank barn, west elevation

9/13



F-1-175

Duthow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc: Md. SHPO, Crownsville, Md.

Dairy barn, north elevation

10/13



F-1-175

Dottow-Thomas Farmstead
Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

Tenant house, view from west

11/13



F. 1-175

Dutrow-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Clarksburg, Md.

Late 19th century wagon shed/corn crib, south
elevation

12/13



F-1-175

Dutton-Thomas Farmstead

Frederick County

Photo: Janet Davis

April 1993

Neg. loc.: Md. SHPO, Crownsville, Md.

Circa 1940 wagon shed/corn crib, south-
east corner view

13/12